



## BUSINESS ACTIVITIES

Repair & Maintenance/Maintenance/Structural equipment/Bearings

<b>General contractor :</b>	-
<b>Customer/Owner :</b>	Department of Rural Roads
<b>Engineer :</b>	-
<b>Freyssinet subsidiary</b>	Freyssinet Thailand (Bangkok)
<b>Start of works period</b>	09/2014
<b>End of works period</b>	01/2015

## PROJECT DESCRIPTION

The structure is prestressed box girder and excessive movement of pot bearing was found on several axis. Owner, Department of Rural Roads called Fryessinet to investigate and realize that the bearing was damaged from mistaking of installation at the time of construction.

## FREYSSINET MISSION

Freyssinet did the pot bearing replacement on 13 column, total 7 new bearings and 18 enlarged top sliding plates were installed with project amount 9.85 M.TH.B.

